

Hindlip, Martin Hussingtree & Salwarpe Parish Council

1 = low, 5 = high

Risk Assessment

To be read in conjunction with description of assests

				a	b	a x b		
	Location	Item	Potential Problem	likely hood of risk	effect of risk	impact of risk	Recommendations	Comments
1	Martin Hussingtree Green	Ditch	falling in ditch	2	1	2	none	Ditch is well back from the footpath (3m+). Good drainage to ditch
2		107 wooden posts	none to general public - far side of ditch	0	0	0	Lengthsman to advise if issues arise if they get damaged during mowing /car accident	All posts in good condition at time of inspection
3		Barrier Gate	good condition & locked	0	0	0		secure. No footpath nearby
4		Various trees	large oak has a few dead branches but these are not overhanging the footpath	1	2	2	tree officer to inspect annually	Clerk to contact tree officer
5		Manhole on green	trip hazard	1	1	1	none	manhole slightly raised but this is not an area where anyone walks
6		Pond surrounded by planted area	fall in pond	1	5	5	none	Pond has 2m bank between it and the bridleway. Posts signal to cars to keep away from edge and these are well maintained. No issues at time of inspection but Lengthsman raises any concerns if posts are damaged by lorries & repairs them.
7		Verge at junction of A38 & A4538	3 manhole covers - trip hazards	1	3	3	Ask Lengthsman to reset manhole cover or build up turf around one side of the cover nearest to A38 to fill hole and eliminate trip hazard	2 manhole covers are completely flush with the ground and pose no risk. Manhole cover nearest the A38 is raised slightly along southern edge and has small 100mm dia hole next to it.
8		Triangular piece A38/A4538	none	0	0	0		
9	Brownheath Common	Common	none	0	0	0		large area left as natural habitat with no access across. Footpaths clear
10	Salwarpe Memorial Land	War monument	none	0	0	0		restored in 2014
11		land around monument	none	0	0	0		
12		metal estate fencing	none	0	0	0		Fencing erected in 2014. Good condition with pyracantha edge growing well in front of it.
13		various trees	1 oak - small dead branch	1	1	1	tree officer to inspect annually	Clerk to contact tree officer
14		oak bench	splinters	1	1	1	none	solid - no risk yet
15		28 wooden posts	cars clipping posts	1	1	1	none	posts well inboard from road
16		water pipe trap (apex of green)		0	0	0		flush to ground
17	Salwarpe Notice boards	Village bridge	splinters	1	1	1		no splinters, perspex front
18		Ladywood canal	splinters	1	1	1		no splinters, perspex front
19		Newland Lane	splinters	1	1	1		new in 2015, good condition
20	Martin H/tree notice boards	opp Knoll Farm	splinters & rotting at base but fixed to fence	1	1	1		no splinters, perspex front
21		Drury Lane	splinters, broken glass	1	2	2		no splinters, glass front OK
22	Hindlip notice boards	Hindlip Lane	splinters	1	1	1		no splinters, perspex front
23	Salwarpe Bins	Bridge dog waste	none	0	0	0		firm stand
24		Bridge refuse	none	0	0	0		firm stand
25	Martin H/tree Bins	A38 bus stop refuse	none	0	0	0		well secured to bus stop

Risk assessment carried out by E Gallagher & A Phillips
issue 2 03/06/2017
issue 1 31/10/2015