1 = low, 5 = high

action must be taken immediately if a x b is 10 or above

	Ris	k A	Assessment
--	-----	-----	------------

To be read in conjunction with description of assests

Risk Assessment		To be read in conjunction with description of assests		a	b	axb		
	Location	Item	Potential Problem	likely hood of risk	effect of risk	impact of risk	Recommendations	Comments
1	Martin Hussingtree Green	Southbound bus shelter	None	0	0	0	none	New shelter installed Nov 2018
2	İ			0	0	0		
		Northbound bus shelter	None	U	U	U	none	New shelter installed Nov 2018
3	1	Ditch	falling in ditch	2	1	2	none	Ditch is well back from the footpath (3m+). Good drainage to ditch
							Lengthsman to advise if	-
4		107 wooden posts	none to general public - far side of ditch	0	0	0	issues arise if they get damaged during mowing /car accident	Rotton posts replaced
5		Barrier Gate	good condition & locked	0	0	0		secure. No footpath nearby
6		Various trees	large oak has a few dead branches but these are not overhanging the footpath	1	2	2	tree warden to inspect annually	Covid 19 delay in appointment
7	,	Manhole on green		1	1	1	Contact Swan & Nursery	Manhole cover repositioned by Worcester County Council. Post removed. Land re-levelled & regrassed
8		Pond surrounded by planted area	fall in pond	1	5	5	Replace 2 posts in next 6 months	Pond has 2m bank between it and the bridleway. Posts signal to cars to keep away from edge and these are well maintained. 2 posts replaced
9		Verge at junction of A38 & A4538	new traffic light covers - trip hazard	0	0	0	none	All manhole covers associated with the new traffic lights are well set into the ground and completely flush. The soil is fully round all covers.
10		Triangular piece A38/A4538	none	0	0	0	none	Manhole covers flush
11	Brownheath Common	Common	none	0	0	0		large area left as natural habitat with no access across. Footpaths clear
	Salwarpe Memorial Land	War monument	none	0	0	0		restored in 2014
13		land around monument	none	0	0	0		
				_	_	_		Fencing erected in 2014. Good condition with
14	ı	metal estate fencing	none	0	0	0		pyracantha edge growing well in front of it.
15		various trees	1 oak - small dead branch	1	1	1	tree officer to inspect annually	Covid 19 delay appointment of tree warden
16		oak bench	splinters	1	1	1	none	solid - no risk yet
17		28 wooden posts	cars clipping posts	1	1	1	none	posts well inboard from road. Posts have been replaced.
18	3	water pipe trap (apex of green)		1	1	1		trap has lost lid but too small to be a trip hazard
19	Salwarpe Notice boards	Village bridge	none	0	0	0		New 2018
20		Ladywood canal	splinters	4	1	4		frame coming apart. Need to replace asap
21		Newland Lane	splinters	1	1	1		new in 2015, good condition
	Martin H/tree notice boards	opp Knoll Farm	splinters & rotting at base but fixed to fence	1	1	1		no splinters, perspex front
23		Drury Lane	splinters	0	0	0		brand new installed March 2019
	Hindlip notice boards	Hindlip Lane	splinters	1	1	1		no splinters, perspex front
_	Salwarpe Bins	Bridge dog waste	none	0	0	0		firm stand
26		Bridge refuse	none	0	0	0		firm stand
27	Martin H/tree Bins	A38 bus stop refuse	none	0	0	0		well secured to bus stop

Risk assessment done by E Gallagher & A Phillips

1ssue 6 30/05/2020 - covid 19 period

Issue 5 30/05/2019

Issue 4 17/09/2018

issue 3 06/01/2018

issue 2 03/06/2017

issue 1 31/10/2015