			1 = low, 5	= high		action must be taken immedi	ately if a x b is 10 or above
Risk Assessment	To be read in conjunction v	vith description of assests	a	b	axb	I	
Location	Item	Potential Problem	likely hood of	effect of risk	impact of risk	Recommendations	Comments
1 Martin Hussingtree Green	Southbound bus shelter	None	0	0	0	none	New shelter installed Nov 2018
3	Northbound bus shelter	None	0	0	0	none	New shelter installed Nov 2018
	northboand bas sheller	Tion C				none	. Good drainage to ditch North ditch well back
							from road edge (3m+). West ditch well back fro
	Ditch	falling in ditch	2	1	2	none	highway footpath (3m+). Good drainage to bot
3							ditches.
						Lengthsman to advise if	
	107 wooden posts	none to general public - far side of ditch	0	0	0	issues arise if they get	Rotton posts replaced
	107 Wooden posts	none to general public - far side of diter			ľ	damaged during mowing	Notion posts replaced
4						/car accident	
5	Barrier Gate	good condition & locked	0	0	0		secure. No footpath nearby
		large oak has a few dead branches but these are				tree warden to inspect	
	Various trees & wild flowers	not overhanging the footpath. Two young oak trees planted Dec 20 have not survived and the	1	2	2	annually. New trees pose	Tree worden neet weent
	various trees & wild flowers	remaining two appear to be in poor condition.	1 2		no risk. Wild flowers pose	Tree warden post vacant	
6		Wild flowers planted April 21				no risk	
<u> </u>		Wild Howers planted April 21					Manhole cover repositioned by Worcester Cou
	A A control of the co					C	Council. Post removed. Land re-levelled & re-
	Manhole on green		1	1	1	Contact Swan & Nursery	grassed. 09/08/21: Manhole now surrounded b
7							wild flowers
							Pond has 2m bank between it and the bridlewa
							Posts signal to cars to keep away from edge and
							these are well maintained. 2 posts replaced.
	Pond surrounded by planted area	fall in pond	1	5	5	Replace 2 posts in next 6	09/08/21 2 posts will need replacing in next 6
						months	months. Busy main road by pond so
							unaccompanied children are unlikely to be nea
8							the pond. Monitor and consider signage
	Verge at junction of A38 & A4538	new traffic light covers - trip hazard	0	0	0	none	All manhole covers associated with the new traf
	verge at junction of A38 & A4338	new traine light covers - trip hazard	0	0	0	lione	lights are well set into the ground and complete flush. The soil is fully round all covers.
9							· ·
10	Triangular piece A38/A4538	none	0	0	0	none	Manhole covers flush
							large area left as natural habitat with no access
Boom booth Common	6		0	_	0		across. Footpaths clear. 09/08/21: Some buildin
Brownheath Common	Common	none	U	0	U		rubbish appears to have been cleared from
							adjacent to footpath. Branches overhanging the
11	14/			_			carriageway to be pruned
12 Salwarpe Memorial Land 13	War monument land around monument	none none	0	0	0		restored in 2014
13							Fencing erected in 2014. Good condition with
14	metal estate fencing	none	0	0	0		pyracantha hedge growing well in front of it.
						tree officer to inspect	
15	various trees	1 oak - small dead branch	1	1	1	annually	tree warden post vacant
16	oak bench	splinters	1	1	1	none	solid - no risk yet
	28 wooden posts	cars clipping posts	1	1	1	none	posts well inboard from road. Posts have been
17							replaced.
10	water pipe trap (apex of green)		1	1	1		trap has lost lid but too small to be a trip hazard
18			+				New 2018. 09/08/21: will need revarnishing wit
Salwarpe Notice boards	Village bridge	none	0	0	0		next 12 months
20	Ladywood canal	splinters	4	1	4		frame coming apart. Need to replace asap
	,		1				
	Newland Lane	splinters & screw closure	1	1	1		new in 2015. Backing in poor condition. 09/08/
21							poorly fitting closure, screw holding shut
22 Martin H/tree notice boards	opp Knoll Farm	splinters & rotting at base but fixed to fence	1	1	1		no splinters, perspex front
23	Drury Lane	splinters	0	0	0		brand new installed March 2019
24 Hindlip notice boards	Hindlip Lane	splinters	1	1	1		no splinters, perspex front poor condition
25 Salwarpe Bins	Bridge dog waste	none	0	0	0		firm stand
26 27 Martin H/tree Bins	Bridge refuse A38 south bus stop refuse	none none	0	0	0		New larger box style, ground fixed. Installed 3/ well secured to bus stop
	,						· ·
Martin H/tree Bins	A38 north bus stop refuse	none	0	0	0	I .	well secured to free standing post. Installed 20:

Risk assessment done by E Gallagher & A Phillips
Issue 7 9/08/21 - EG & AP
Issue 6 30/05/2020 - covid 19 period (Cllr Phillips only)
Issue 5 30/05/2019
Issue 4 17/09/2018

issue 3 06/01/2018

issue 2 03/06/2017 issue 1 31/10/2015