

Hindlip, Martin Hussingtree & Salwarpe Parish Council		Issue 8 - 9/11/2022							
Risk Assessment		To be read in conjunction with description of assests				1 = low, 5 = high		action must be taken immediately if a x b is 10 or above	
						a	b	a x b	
Location		Item	Potential Problem	likely hood of risk	effect of risk	impact of risk	Recommendations	Comments	
1	Martin Hussingtree Green	Southbound bus shelter	None	0	0	0	none	New shelter installed Nov 2018. 11/22 - good condition & recently cleaned	
2		Northbound bus shelter	None	0	0	0	none	New shelter installed Nov 2018. 11/22 as above	
3		Ditch	falling in ditch	2	1	2	none	Ditch is well back from the footpath (3m+). Good drainage to ditch.	
4		107 wooden posts	none to general public - far side of ditch	0	0	0	Lengthsman to advise if issues arise if they get damaged during mowing /car accident	Rotton posts replaced. 11/22 2 posts replaced after RTA	
5		Barrier Gate	good condition & locked	0	0	0		secure. No footpath nearby	
6		Various trees & wild flowers	Wild flowers planted April 21 & added to April 22. 4 young oaks planted early 22. 14 fruit trees planted Nov 21. 11/22 - all young trees surviving. Large oak has been maintained. Old branches have been left to rot at base of tree	1	2	2	tree warden to inspect annually. New trees pose no risk. Wild flowers pose no risk	11/22 Tree warden in post. Regular tree maintenance required until trees are fully established	
7		Manhole on green		1	1	1	Contact Swan & Nursery	Manhole cover repositioned by Worcester County Council. Post removed. Land re-levelled & re-grassed. 09/08/21: Manhole now surrounded by wild flowers	
8		Pond surrounded by planted area	fall in pond	1	5	5	Replace 3 posts in next 6 months	Pond has 2m bank between it and the bridleway. Posts signal to cars to keep away from edge and these are well maintained. 2 posts replaced. 11/22 3 posts will need replacing in next 6 months. Busy main road by pond so unaccompanied children are unlikely to be near the pond.	
9		Verge at junction of A38 & A4538	new traffic light covers - trip hazard	0	0	0	none	All manhole covers associated with the new traffic lights are well set into the ground and completely flush. The soil is fully round all covers. 11/22 rabbit hole near hedge - unlikely trip hazard Posts need to be inspected and some replaced/repositioned within 6-9 months	
10		Triangular piece A38/A4538	none	0	0	0	none	Manhole covers flush	
11	Brownheath Common	Common	none	0	0	0		large area left as natural habitat with no access across. Footpaths clear. Building rubbish has been cleared from adjacent to footpath. 11/22 - new 5 bar gate across footpath. Secure & good access to footpath, although no way marker in place	
12	Salwarpe Memorial Land	War monument	none	0	0	0		restored in 2014	
13		land around monument	none	0	0	0			
14		metal estate fencing	none	0	0	0		Fencing erected in 2014. Good condition with pyracantha hedge growing well in front of it.	
15		various trees	1 oak	1	1	1	tree officer to inspect annually	11/22 tree warden in post	
16		oak bench	splinters	1	1	1	none	solid - no risk yet	
17		28 wooden posts	cars clipping posts	1	1	1	none	posts well inboard from road. Posts have been replaced.	
18		water pipe trap (apex of green)		1	1	1		trap has lost lid but too small to be a trip hazard	
19	Salwarpe Notice boards	Village bridge	none	0	0	0		New 2018. 11/22 - needs revarnishing	
20		Ladywood canal	none	0	0	0		new in 2022	
21		Newland Lane	none	0	0	0		new in 2022	
22	Martin H/tree notice boards	opp Knoll Farm	none	0	0	0		new in 2022	
23		Drury Lane	none	0	0	0		installed March 2019. 11/22 - needs revarnishing	
24	Hindlip notice boards	Hindlip Lane	none	0	0	0		11/22 notice board has been removed	
25	Salwarpe Bins	Bridge dog waste	none	0	0	0		firm stand	
26		Bridge refuse	none	0	0	0		firm stand	
27	Martin H/tree Bins	A38 south bus stop refuse	none	0	0	0		well secured to bus stop	
28	Martin H/tree Bins	A38 north bus stop refuse	none	0	0	0		well secured to free standing post. Installed 2019	

