

Risk Assessment			1 = low, 5 = high			action must be taken immediately if a x b is 10 or above	
To be read in conjunction with description of assests			a	b	a x b		
Location	Item	Potential Problem	likely hood of risk	effect of risk	impact of risk	Recommendations	Comments
1 Martin Hussingtree Green & Pond	Southbound bus shelter	None	0	0	0	none	New shelter installed Nov 2018. 01/24 - graffiti removed in Jan 24.
2	Northbound bus shelter	None	0	0	0	none	New shelter installed Nov 2018. 4/25 Scratched graffiti on LH window - no risk
3	Ditch	falling in ditch	2	1	2	none	Ditch is well back from the footpath (3m+). Good drainage to ditch. Top Cut are using weedkiller in the ditch. Natural Networks have expressed concerns about weed killers getting into the water course. 4/25 no evidence of weedkiller being used
4	107 wooden posts	none to general public - far side of ditch	0	0	0	Contractor to advise if issues arise if they get damaged during mowing /car accident	Contractor to replace when advised to do so.
5	Barrier Gate	good condition & locked	0	0	0		secure. No footpath nearby
6	Various trees & wild flowers	Wild flowers planted April 21 & added to April 22 & autumn 23. 4 young oaks planted early 22. 14 fruit trees planted Nov 21. 2 replaced Dec 23	1	2	2	tree warden to inspect annually. New trees pose no risk. Wild flowers pose no risk	Fruit trees mulched Dec 23. Additional trees & whips planted March 24 & Jan 25
7	Manhole on green		1	1	1	Contact Swan & Nursery	Manhole cover repositioned by Worcester County Council. Post removed. Land re-levelled & re-grassed. 09/08/21: Manhole now surrounded by wild flowers
8	Pond surrounded by planted area	fall in pond	1	5	5	Posts replaced by contractor on a regular basis. Cherry Lane have donated posts	Pond has 2m bank between it and the bridleway. Posts signal to cars to keep away from edge and these are well maintained. Bus main road by pond so unaccompanied children are unlikely to be near the pond. 4/25 3 posts have been knocked but no risk to public - general maintenance issue
9	Verge at junction of A38 & A4538	new traffic light covers - trip hazard	0	0	0	none. 3 posts need replacing	All manhole covers associated with the new traffic lights are well set into the ground and completely flush. The soil is fully round all covers.
10	Triangular piece A38/A4538	none	0	0	0	none	Manhole covers flush
11 Brownheath Common	Common	none	0	0	0		large area left as natural habitat with no access across. Footpaths clear. Building rubbish has been cleared from adjacent to footpath. 11/22 - new 5 bar gate across footpath. Secure & good access to footpath, although no way marker in place. BT lines catching trees on drive to All Saints Farm
12 Copcut Rise Estate	Litter Bin	none	0	0	0		Newly installed in 2024
13	Bus Shelter with benches	none	0	0	0		Newly installed in 2024
14	Alfie's memorial bench	none	0	0	0		Newly installed in 2024. Composite hard wearing material
15	King's Coronation bench	none	0	0	0		Newly installed in 2024. Composite hard wearing material
16	Bench near playground	none	0	0	0		Newly installed in 2024. Composite hard wearing material
17 Salwarpe Memorial Land	War monument	none	0	0	0		restored in 2014
18	land around monument	none	0	0	0		Acar planted for Coronation Sept 23
19	metal estate fencing	none	0	0	0		Fencing erected in 2014. Good condition with pyracantha hedge growing well in front of it.
20	various trees	1 oak	1	1	1	tree officer to inspect annually	
21	oak bench	splinters	1	1	1	none	solid - no risk yet
22	28 wooden posts	cars clipping posts	1	1	1	none	posts well inboard from road. Posts have been replaced.
23	water pipe trap (apex of green)		1	1	1		trap has lost lid but too small to be a trip hazard
24 Salwarpe Notice boards	Village bridge	none	0	0	0		01/24 revarnished. 4/25 needs revarnishing
25	Ladywood canal	none	0	0	0		new in 2022
26	Newland Lane	none	0	0	0		new in 2022
27 Martin H/tree notice boards	opp knoll Farm	none	0	0	0		new in 2022
28	Drury Lane	none	0	0	0		01/24 revarnished. 4/25 needs revarnishing
29 Copcut estate notice board	by bus stop	none	0	0	0		new in 2024
30 Salwarpe Bins	Bridge dog waste	none	0	0	0		firm stand
31	Bridge refuse	none	0	0	0		01/24 new bin
32 Martin H/tree Bins	A38 south bus stop refuse	none	0	0	0		well secured to bus stop
33	A38 north bus stop refuse	none	0	0	0		well secured to free standing post. Installed 2019
34 Salwarpe Bins	Boundary with Village Hall Carpark	none	0	0	0		Newly Installed 2024

Risk assessment done by E Gallagher & A Phillips

Issue 10 21/04/25 - EG & AP

Issue 9 31/01/24 - EG & AP

Issue 8 04/11/22 - EG & AP

Issue 7 9/08/21 - EG & AP

Issue 6 30/05/2020 - covid 19 period (Cllr Phillips only)

Issue 5 30/05/2019

Issue 4 17/09/2018

Issue 3 06/01/2018

Issue 2 03/06/2017

Issue 1 31/10/2015